

Precision Manufacturing

LABORATORY SAFETY - Visitors

In all cases the instructor will have sole discretion as to suitability of attire or behavior.

- 1. Safety glasses must be worn at all times while in the machine tool lab.**
- 2. Never wear loose clothing around machines. Remove loose sweatshirts, coats and ties.**
- 3. Appropriate footwear shall be worn in the lab.**
- 4. Do not wear rings, watches, necklaces, etc., which could be caught in a machine.**
- 5. Loose or long hair must be either tied back, tucked under a hat, or in a hair net.**
- 6. Never have more than one person operating a machine at one time.**
- 7. Absolutely no horseplay will be allowed in the lab.**
- 8. No work is to be performed in the lab without an instructor present.**
- 9. Report all injuries, no matter how slight, to the instructor immediately.**
- 10. No machine or tool in the lab will be operated/utilized until the student has been fully briefed by the instructor in its proper use, and operating procedures.**

This project was funded completely by a \$2.5 million, grant awarded under the Trade Adjustment Assistance Community College and Career Training Grants, as implemented by the U.S. Department of Labor's Employment and Training Administration. Nashua Community College is an equal opportunity employer/program and auxiliary aids and services are available upon request to individuals with disabilities.

