



Hazard Key:

1. Hot Pipe
2. Potential steam hazard from leaks in pipe
3. Falling debris of any kind
4. Improperly stored chemicals
5. No protective cover around gears
6. Improperly stored tools left on ground; trip hazard
7. Slip hazard from leaks
8. Dim lighting
9. Improper tag/lock out
10. Miner reaching over conveyor belt
11. No ear protection
12. No eye protection
13. No respiratory protection if required
14. Employee fatigue
15. No hand protection

This workforce solution was funded by a grant awarded by the U.S. Department of Labor's Employment and Training Administration. The solution was created by the grantee and does not necessarily reflect the official position of the U.S. Department of Labor. The Department of Labor makes no guarantees, warranties, or assurances of any kind, express or implied, with respect to such information, including any information on linked sites and including, but not limited to, accuracy of the information or its completeness, timeliness, usefulness, adequacy, continued availability, or ownership.

This [Prince William Sound College](http://www.princewilliamsoundcollege.edu/) work is licensed under the Creative Commons Attribution 4.0 International License. To view a copy of this license, visit: <http://creativecommons.org/licenses/by/4.0/>