



Refer to <http://www.aws.org/technical/errata/A2.4errata.pdf>. Draw the requested welded symbol. Draw the requested grooves. Draw the weld in the indicated position.

**Example:** Fillet weld on a T joint on the arrow side.




Draw all symbols for the weld on the arrow side


1. Single Bevel on a corner joint



2. V groove on a butt joint



3. U groove on a butt joint



4. Square groove on a butt joint

