Welding Technology Program WLDG 180 Rotation Schedule Autumn 2015



Student Name

Week	Date Range	Length	Job#	Description
Week 1	08-31 to 09-05	5 Days	NA NA	Safety/Shop Orientation
Week 2	09-08 to 09-11	4 Days	181-100 29109-1 29109-2	Flat Build-up Plate (1/8" E6013 on 3/8" Plate) Flat Build-up Plate (1/8" E6010 on 3/8" Plate) Flat Build-up Plate (1/8" E6018 on 3/8" Plate)
Week 3	09-14 to 09-18	5 Days	29109-3 29109-4 29109-5	2F T-Joint (1/8" E6010 on 1/4" Plate-weld size 1/4 & 3/8) 2F T-Joint (1/8" E6018 on 1/4" Plate-weld size 1/4 & 3/8) 3F T-Joint (1/8" E6010 on 1/4" Plate-weld size 1/4 & 3/8)
Week 4	09-21 to 09-25	5 Days	29109-6 29109-7 29109-8	3F T-Joint (1/8" E6018 on 1/4" Plate-weld size 1/4 & 3/8) 4F T-Joint (1/8" E6010 on 1/4" Plate-weld size 1/4 & 3/8) 4F T-Joint (1/8" E6018 on 1/4" Plate-weld size 1/4 & 3/8)
Week 5	09-28 to 10-02	5 Days	TEST 29105-1 29102-1 29102-2	MULTIPLE WELDS on 1/4" PLATE Track Torch Cut (3/8" Plate, 6" minimum length-12" maximum 22.5° & 30°) OAC layout cut on plate steep-3/16"-Refer to print for layout OAC layout cut on plate steep-3/8"-Refer to print for layout
Week 6	10-05 to 10-09	5 Days	29103-1 29111-1 29111-2	PAC Contour cut on plate steel-3/16"-Refer to print for layout 1G V-groove with Backing (1/8" E7018 on 3/8" Plate) 2G V-groove with Backing (1/8" E7018 on 3/8" Plate)
Week 7	10-12 to 10-16	5 Days	29111-3 29111-4	3G V-groove with Backing (1/8" E7018 on 3/8" Plate) 4G V-groove with Backing (1/8" E7018 on 3/8" Plate)
Week 8	10-19 to 10-23	5 Days	TEST 29104-1	V-GROOVE TEST 1G V-groove w/o backing closed root, 1/8" E7018, AAC backside, back weld with 1/8" E7018 on 3.8" Plate)
Week 9	10-26 to 10-30	5 Days	181-200 181-201 181-202	OAW stringer beads on flat plate – with and without filler OAW 2F lap joint (with filler) OAW 3F lap joint (with filler)
Week 10	11-02 to 11-06	[181-203 181-204 181-205	OAW 1F outside corner joint (with filler) OAW 3F outside corner joint (with filler) OAW 2F T-joint (with filler)
Week 11	11-09 to 11-13	4 Days	TEST 29112-1 29112-2	MULTIPLE WELDS ON 10 GAUGE METAL 1G w/o backing (1/8" E6010 and 1/8" E7018 on 3/8" plate) 2G w/o backing (1/8" E6010 and 1/8" E7018 on 3/8" plate)
Week 12	11-16 to 11-20	5 Days	29112-3 29112-4	3G w/o backing (1/8" E6010 and 1/8" E7018 on 3/8" plate) 4G w/o backing (1/8" E6010 and 1/8" E7018 on 3/8" plate)
Week 13	11-23 to 11-24	2 Days	181-108	3F Lap joint vertical down (3/32" E6010 and 3/32" E6013)
Week 14	11-30 to 12-04	5 Days	181-105	Vertical Buildup Plate (1/8" E6010)
Week 15	12-07 to 12-11	5 Days	NA	Last Week and Shop Cleanup
	12-14 to 12-18	5 Days	NA	FINALS WEEK
MACHINES USED:			V350 DC-400 XMT304	

